

## TEST REPORT

No. : XMIN2505001149CM01\_EN

Date : 2025-06-05

Page: 1 of 3

CUSTOMER NAME: LONGDA CHINA GROUP HK CO., LIMITED  
ADDRESS: 705A SILVERCORD TOWER 2, 30 CANTON ROAD, TSIM SHA TSUI,  
KL, HONGKONG

Sample Name : Safety Flooring Homogeneous Vinyl Sheet

Material : PVC

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*

Date of Receipt : 2025-05-27

Testing Period : 2025-05-27 ~ 2025-05-30

Test result(s) : For further details, please refer to the following page(s)  
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for  
SGS-CSTC Standards Technical  
Services Co.,Ltd. Xiamen Branch.

Bryan Hong  
Authorized signatory



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CSTC Standards Technical Services Co., Ltd.  
Xiamen Branch Testing Laboratory

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China 361101  
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t (86-592) 5765857 www.sgsgroup.com.cn  
t (86-592) 5765857 sgs.china@sgs.com

## TEST REPORT

No. : XMIN2505001149CM01\_EN

Date : 2025-06-05

Page: 2 of 3

### Summary of Results:

No.	Test Item	Test Method	Result
1	Anti-Slip Property	DIN 51130:2014-02	Critical angle of inclination: 11.2° Classification: R10

### Original Sample Photo:



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China 361101  
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t (86-592) 5765857 www.sgsgroup.com.cn  
t (86-592) 5765857 sgs.china@sgs.com

## TEST REPORT

No. : XMIN2505001149CM01\_EN

Date : 2025-06-05

Page: 3 of 3

### 1. Test Item: Anti-Slip Property

Sample Description: See photo

Test Method: DIN 51130:2014-02 Testing of floor coverings - Determination of the anti-slip property -

Workrooms and fields of activities with slip danger, walking method - Ramp test

Test Condition:

Specimen: 1000mm×500mm, 1pc, see photo

Test surface: see photo

Test direction: long side direction

Test Result:

Test Item	Test Result	Classification
Anti-Slip Property	Critical angle of inclination: 11.2°	R10

### Classification of Anti-Slip Property (oil-wet ramp test):

Classification	Angle (degrees)
R9	$6^{\circ} \leq X \leq 10^{\circ}$
R10	$10^{\circ} < X \leq 19^{\circ}$
R11	$19^{\circ} < X \leq 27^{\circ}$
R12	$27^{\circ} < X \leq 35^{\circ}$
R13	$> 35^{\circ}$

\*\*\*\*\*End of report\*\*\*\*\*



Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing / inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)

SGS-CSIS Standards Technical Services Co., Ltd.  
Xiamen Branch Testing Laboratory

No.31 Xianghong Road, Xiang'an Torch Industrial Zone, Xiamen, Fujian Province, China 361101  
中国·福建·厦门·火炬(翔安)产业区翔虹路31号 邮编: 361101

t (86-592) 5765857 www.sgsgroup.com.cn  
t (86-592) 5765857 sgs.china@sgs.com